## INDIAN INSTITUTE OF TECHNOLOGY BOMBAY ESTATE OFFICE

13<sup>h</sup> March. 2024

### **CORRIGENDUM**

#### EO/A/HOSTEL/WKS-145/23-24

Name of Work: Providing and applying waterproofing chemical treatment to external walls of Hostel No. 18.

This is with reference to above-mentioned work in which there is a change in description of Serial Item No. 10 of schedule of work. Details as mentioned below:

# Previous despcription of work in item No. 10

about 120-150 microns DFT as per manufacturer as per after work etc. all complete as directed. (For vertical complete as directed. (For vertical surface). surface).

## Amendment in description of work in item No. 10

ITEM No. 10) Providing and applying one or more ITEM No. 10) Providing and applying one or more coat of Dr. Fixit Raincoat Universal Base Coat coat of Dr. Fixit Raincoat Universal Base Coat over plaster, masonary or RCC surface of any height over plaster, masonary or RCC surface of any height including scaffolding and without any dilution at a without any dilution at a spreading rate of 3.5 -4.0 sq spreading rate of 3.5 -4.0 sq mtr per litre to achieve mtr per litre to achieve about 120-150 microns DFT manufacturer specification including specification including preparing the surface by preparing the surface by thoroughly cleaning thoroughly cleaning laitance, loose material, oil, laitance, loose material, oil, grease and other foreign grease and other foreign matter with wire brush and matter with wire brush and vacuum cleaning, filling vacuum cleaning, filling the cracks using appropriate the cracks using appropriate exterior putty, covering exterior putty, covering the floor and wall, window the floor and wall, window glass with plastic sheet glass with plastic sheet during work and cleaning during work and cleaning after work etc. all

Superintending Engineer (I/C)