



INDIAN INSTITUTE OF TECHNOLOGY BOMBAY

MATERIALS MANAGEMENT DIVISION

Powai, Mumbai 400076.

Ref. No. (PR No. 1000041034)

Rx.No. 6100001858

**TECHNICAL SPECIFICATION OF REPAIR AND RETURN FOR STANDARD CHI
(X) CRADLE**

Sr. No.	Technical Specification	Compliance (Yes/No)	Additional Information if Any
1.	<p>Repair and Return for Standard Chi (X) Cradle</p> <p>Overhaul and repair of the Chi Cradle for Rigaku SmartLab 9kw HRXRD. The overhaul includes dismantling the whole goniometer, replacing the faulty gears and finally assembling and realigning the system. Part No. : A00008637 changed from (C/N : :2680A101, Serial No. JD12636)</p> <p>Warranty : 6 Months warranty after installation and commissioning</p>		